PORT AUTHORITY.

Gradient Soft Shell Jacket J311

PRODUCT MEASUREMENTS

	XS	S	М	L	XL	2XL	3XL	4XL
Chest	20	21 1/2	23	24 1/2	26	27 1/2	29 1/2	31 1/2
Length	26	27	28	29	30	31	31 1/2	32
Sleeve Length	34	34 3/4	35 1/2	36 1/4	37	37 3/4	38 1/2	39 1/4

CHEST LENGTH

Measured across the chest one inch below armhole when laid Measured

flat.

Measured from center front neck to hem.

SLEEVE LENGTH

Start at center of neck and measure down shoulder, down

s leeve to hem.